Vasavi Borewells

Sampigehalli, Jakkur Post,
Bangalore-560 064

Mobile : 97413 28671
73376 51372

WORK REPORT

PARTY'S NAME..... Sri. Balaji Infrastructures.....

SITE ADDRESS..... Lake view layout 2nd main Venkatala...

DEPTH..... 349 meters ..... CASING..... 6ometer.....

OVER SIZE CASING..... — ..... COLLOR..... 11 nos.....

CAP..... WELDING.....

WATER SOURCE..... 2.5" ..... A : — ..... B : —

QUALITY OF WATER..... — Good Condition —.....

REMARKS.....

THIS ABOVE REPORT HAS SEEN ACCEPTED BY ME/PARTY REPRESENTATIVE

For Sri Balaji Infrastructures
Proprietor
PARTY SIGNATURE

AE-1
A.E.E

SRI VASAVI BORWELLS
Proprietor

Vasavi Borewells

Sampigehalli, Jakkur Post,
Bangalore-560 064

Mobile : 97413 28671
73376 51372

WORK REPORT

PARTY'S NAME..... Sri. Balaji Infrastructures.

SITE ADDRESS..... Lake view layout Suresh house I main 2nd Venkatala

DEPTH..... 347 meter CASING..... 6ometer

OVER SIZE CASING..... — COLLOR..... 11 Nos

CAP..... — WELDING..... don —

WATER SOURCE..... — 2" — A : — B : —

QUALITY OF WATER..... — Good condition —

REMARKS.....

THIS ABOVE REPORT HAS SEEN ACCEPTED BY ME/PARTY REPRESENTATIVE

For Sri Balaji Infrastructures

PARTY SIGNATURE

AE-1

1

A.E.E

SRI VASAVI BORWELL

Proprietor

Vasavi Borewells

Sampigehalli, Jakkur Post,
Bangalore-560 064

Mobile : 97413 28671
73376 51372

WORK REPORT

PARTY'S NAME.....Sri: Balaji Infrastructures.....

SITE ADDRESS.....Shivanahalli 1st main road - Yelahanka.....

DEPTH.....-345mtrs-.....CASING.....-6ometer-.....

OVER SIZE CASING.....-.....COLLOR.....11 Nos.....

CAP.....WELDING.....

WATER SOURCE.....-2"-.....A :.....-.....B :.....-.....

QUALITY OF WATER.....-2"-Good condition-.....

REMARKS.....-.....

THIS ABOVE REPORT HAS SEEN ACCEPTED BY ME/PARTY REPRESENTATIVE

For Sri Balaji Infrastructures
Proprietor

PARTY SIGNATURE

AE-1

A.E.E

SRI VASAVI BORWELLS
Proprietor